


TPMS SERVICE KITS

TPMS SERVICE KITS



The OEM requires that the valve stem components are replaced every time the tire is serviced on vehicles with TPMS.



Clamp-In Kit Components	Replacement Reason	Result
(A) Valve Core	Nickel plating strips leading to galvanic corrosion & seized valve cores	Leak at valve core, potential broken valve stem
(B) Valve Cap w/seal	Valve cap seal wear	Allows moisture into core
(C) Hex Nut	Plating worn off, treads corrode	Leak path at valve stem
(D) Grommet/ seal	Crack, deteriorate and leak over	leak path at valve stem
(E) Metal washer (some applications)	Washer conforms to rim during installation	Leak path at valve stem
Clamp-In Kit Components	Replacement Reason	Result
(F) Rubber TPMS snap-in valve	Crack, deteriorate and leak over time	Leak pather at valve stem

Refer to manufacturer's specifications for proper torque requirements when replacing hex nuts and valve cores. These specifications can be found in the Dynamic TPMS Service Kit Application Guide.

<p>6-102 Buick, Cadillac, Chevy, GMC, Hummer, Isuzu, Pontiac, Saab</p> <p>Cross-reference: 20004, 20006, 1070K, 92-0125</p>	<p>6-103 Cadillac, Chevy, Chrysler, Dodge, Infiniti, Isuzu, Jeep, Mitsubishi, Nissan, S</p> <p>Cross-reference: 20003, 1080K, 92-0140</p>	<p>6-106 Ford, Lincoln, Mercury, Mercedes</p> <p>Cross-reference: 20002, 1060K, 92-0115</p>
<p>6-108 Buick, Cadillac, Chevy, Chrysler, Dodge, GMC, Hyundai, Jaguar, Jee </p> <p>Cross-reference: 20030, 1050K, 92-0150</p>	<p>6-109 Acura, Honda, Hyundai, Kia</p> <p>Cross-reference: 20021, 2000K, 92-0246</p>	<p>6-110 Mercedes, Mini, Porsche, VW</p> <p>Cross-reference: 20023, 1090K, 92-0261</p>
<p>6-111 Pontiac, Scion, Toyota</p> <p>Cross-reference: 20032, 1100K, 92-0215</p>	<p>6-112 Honda, Infiniti, Mitsubishi, Nissan</p> <p>Cross-reference: 20010, 1130K, 92-0130</p>	<p>6-115 Audi, VW</p> <p>Cross-reference: 20017, 1030K, 92-0235</p>
<p>6-116 Lexus, Toyota</p> <p>Cross-reference: 20031, 1110K, 92-0135</p>	<p>6-117 Lexus</p> <p>Cross-reference: 20033, 1120K, 92-0155</p>	<p>6-120 Chrysler, Dodge, Infiniti, Jean Lincoln, Mazda, Mercury, Pontiac, Saturn, Subaru, Su:</p> <p>Cross-reference: 20016, 2030K, 92-202</p>

TPMS SERVICE KITS & REPLACEMENT VALVES

TPMS SERVICE KITS

6-122

Saab, Saturn,
Suzuki, Volvo

Cross-reference:
20009, 2010K,
92-0195



6-125

Cadillac, Chevy, GM,
GMC

Cross-reference:
20015, 2020K



6-127

Acura, Honda,
Hyundai, Kia

Cross-reference:
20019, 2040K,
92-0244



6-129

VW

Cross-reference:
20017, 1031K



6-138

Cadillac, Chevy, Chrysler, Honda,
Hyundai, Jaguar, Kia, Lan
Mazda, Mitsubishi,
Suzuki, VW, Volvo

Cross-reference:
20032, 7020K, 92-3312



6-139

Chrysler, Dodge, Jeep,
Nissan

Cross-reference:
20013, 7000K,
92-3311



6-207A

GM, Chrysler, Dodge, Ford,
GMC, Hummer, Jeep, Mazda,
Mercury, Subaru, Suzuki

Cross-reference:
20008, 20018, VS950, 92-0145



TPMS REPLACEMENT VALVES

6-201

Chrysler, Dodge
Jeep, Mitsubishi

Cross-reference:
N/A



6-203

Chrome Valve for Ford Shelby
Cobra Optional replacement
for 6-207A & DVT-PRO Sensor

Cross-reference:
VS925C



6-204

Acura, Honda
(Long Valve)

Cross-reference:
20035, 1097K



6-205

Acura, Honda
(Short Valve)

Cross-reference:
20036, 1096K



6-206B

Mercedes, Smart

Cross-reference:
20023, 1040K, 92-1170



6-207A

Chrysler, Dodge, Ford, GM, Hummer,
Jeep, Mazda, Mercury,
Subaru, Suzuki

Cross-reference:
20008, 20018, VS950, 92-0145



6-208

Cadillac ATS,
Dodge Dart

Cross-reference:
VS90



6-209

Hyundai


Cross-reference:
VS1010



6-210

Hyundai, Kia

Cross-reference:
20046



TPMS REPLACEMENT VALVES

TPMS REPLACEMENT VALVES

<p>6-211 Dodge TRW Snap-In, Jeep, Ram</p> <p>Cross-reference: VS65</p> 	<p>6-213 Ford 2015</p> <p>Cross-reference: VS20</p> 	<p>6-218 Dodge Sprinter</p> <p>Cross-reference: 20036, 1098K, 92-1170</p> 
<p>6-220 Audi 4, BMW, Porsche Gen I (Silver - 43 mm)</p> <p>Cross-reference: 1092, RDV001</p> 	<p>6-221 BMW Gen I (Green - 48 mm)</p> <p>Cross-reference: 1093, RDV002</p> 	<p>6-222 BMW, Mercedes Gen I (Black - 49 mm)</p> <p>Cross-reference: 1094, RDV003</p> 
<p>6-223 BMW, Mercedes Gen I (Orange - 51 mm)</p> <p>Cross-reference: 1095, RDV004</p> 	<p>6-225/6-225B Aluminum Optional Replacement Valve for 6-207A & DVT-PRO Sensor</p> <p>Cross-reference: VS925A, 34000</p> 	<p>6-228S Chrysler, Dodge, Jeep, Mercedes</p> <p>Cross-reference: 9066K</p> 
<p>6-231C Adjustable Valve for Chrysl Dodge, Honda, Jeep</p> <p>Cross-reference: VS70</p> 	<p>6-235 Alfa Romeo, Chevrolet, Infinit Maserati, Mercedes Benz, Rar</p> <p>Cross-reference: VS40</p> 	<p>6-236 Hyundai, Kia</p> <p>Cross-reference: VS965</p> 
<p>6-240 Audi, BMW, Mercedes, VW Gen II (Silver - 43mm)</p> <p>Cross-reference: RDV021</p> 	<p>6-241 BMW Gen II (Green - 48mm)</p> <p>Cross-reference: RDV022</p> 	<p>6-242 Audi, BMW, Porsche, VW Gen II (Black - 49mm)</p> <p>Cross-reference: RDV023</p> 
<p>6-243 BMW Gen II (Orange - 51mm)</p> <p>Cross-reference: RDV024</p> 	<p>6-244 Rubber Snap-In Valve Ford, Lincoln, Subaru</p> <p>Cross-reference: VS20</p> 	<p>6-245 Metal Clamp-In High-Pressure Valve Ford, Lincoln</p> <p>Cross-reference: VS240MC</p> 

TPMS ASSORTMENTS

TPMS SERVICE KIT & REPLACEMENT VALVES ASSORTMENTS

Dynamic Service Kit & Replacement Valve Assortments contain all of the popular fittings required for TPMS tire servicing. For both domestic and import cars and light trucks.

Each assortment comes in a durable plastic case that keeps all of the fittings organized and easy to find. The detailed lid insert identifies each fitting with a graphic reference and size. Reorder part numbers, quantities and UPC codes are also shown.

Available Assortments:

See Automotive Service Parts Assortment Catalog for specific part numbers and quantities



Valve Maintenance Kit Assortment- No. DY-TPMS-16

OE Replacement Valve Maintenance Kit most popular TPMS service kits for most domestic and imported cars and light trucks.

- 17 part numbers
- 350 total pieces



Valve Stem Assortment - No. DY-TPMS-16VSR

Assortment of popular TPMS replacement valve stems.

- 16 part numbers
- 52 total pieces



Valve Stem Assortment - No. DY-TPMS-VSEURO

Assortment includes replacement of corroded or broken OE TPMS valve stem.

- 8 part numbers
- 32 total pieces